



CANRIG DRILLING TECHNOLOGY LTD

PRODUCT BULLETIN NUMBER: 14

DATE: July 8, 1993

SUBJECT: Block Guide disconnection for Mast Erection

SERIAL NUMBERS: 007, 008

DISCUSSION: The position of the mast raising line sheaves of the sides of the mast often results in a loading of the traveling block during mast erection significantly off well center. This loading could overstress the Toque Guide and its mounts if the block guides are attached.

RECOMMENDATION: Unless approval is obtained from Canrig, disconnect the block guides for mast raising.

INFORMATION:

For further information contact:

Field Operations Manager
Canrig Drilling Technology Ltd.
14703 FM 1488
Magnolia, Texas 77354
Phone: 281.259.8887
Fax: 281.259.8158

This page intentionally left blank