

Technical Bulletin			 <p>Tesco Corporation 5616 – 80th Avenue SE Calgary, Alberta, Canada T2C 4N5 Tel: 1-877-TESCO-77 (North America) Tel: 1 (713) 359-7195 (AMSS 24-hour support) Tel: 1 (713) 359-7295 (International) Email: bulletins@tescocorp.com www.tescocorp.com www.tescoparts.com</p>
No: TB120	Rev: 0	Date: June 22, 2017	
Koncar Blower Motor Service Revision ESI Top Drive			
<input checked="" type="checkbox"/> Internal Use Only <input type="checkbox"/> External Use			<input type="checkbox"/> Mandatory <input checked="" type="checkbox"/> Recommended

BACKGROUND INFORMATION

Based on customer feedback and service observations on the difficulty encountered when changing a faulty blower motor or impeller, Tesco has introduced a motor service procedure revision that can be performed on location when time permits.

AFFECTED PRODUCTS

This bulletin applies to the ESI top drive models equipped with the Koncar main motor only, other models are not affected.

ACTION REQUIRED

During the next service period selected the Koncar blower assembly suction collector must be modified to allow removal of the blower motor separate of the main motor housing. This activity is outlined in Tesco service document 5067339Rev0.

Version	Date (D/M/Y)	ECN	Description of changes
Rev 0	22/06/2017	115-0022	Initial release of document

Copyright © 2017 Tesco Corporation. TESCO® is a registered trademark in the United States and Canada. Casing Drive System™, CDS™, Multiple Control Line Running System™ and MCLRS™ are trademarks in the United States. All information in this document is proprietary and confidential, and shall remain the sole property of Tesco Corporation. This document shall not be used, copied, or reproduced in whole or in part, nor shall be revealed in any manner to outside parties without prior written permission from Tesco Corporation.