



SAFETY BULLETIN SB002

From: Tesco Products-Applications

Date: Jan 23 02

Re: Winter Buildings

A potential hazard has been noted on Hydraulic Units installed in winter buildings Tesco number 3163. There is no means of egress from the right rear of the building in case of an emergency.

Tesco recommends the installation of an escape hatch with a quick release handle in the last panel on the right side opposite the man door. An upgrade kit can be supplied by Tesco if requested. Please see attached drawing for details.

***If there are any questions related to this Safety Bulletin please contact
Tesco Products-Applications
(403)-233-0757
[Mike Crocker Applications Group](#)***

