

Technical Bulletin

No: TB058

Rev: 0

Date: 15 July 2008

Dual Ball Valve Rotary Actuator Greaseless Hub



TESCO[®]

Tesco Corporation
6204 – 6A Street SE
Calgary, AB. T2H 2B7
Phone: (403) 692 5700
www.tescocorp.com

BACKGROUND INFORMATION:

TESCO, top drive systems has introduced the next generation of Rotary Actuator incorporating roller bearings which eliminate certain operational maintenance requirements, improve field serviceability and enhance product performance.

AFFECTED PRODUCT:

Rotary Actuators; TESCO part numbers: 4166, 5997, 8528, and 10193.

ACTION REQUIRED:

Recommend upgrading legacy actuators to roller bearing roto hub for improved performance at 1000 day recertification.

The Next Generation of Rotary Actuator will phase into production as they become available, (existing part numbers will remain the same). All other actuators currently in use can be upgraded to include these enhanced features by using specific Upgrade Kits, which are available through TESCO After Market Sales and Service (Refer to Upgrade Bulletin UB010).

Contact your local TESCO Parts and Service Center for further information regarding this bulletin and or supply of affected components noted above.