

BACKGROUND INFORMATION:

TESCO was informed that the blower motors on the Ward Leonard 400HP main motors have been changed from a 5HP blower motor to a 10HP blower motor in order to comply with CSA certification.

PRODUCT COVERED:

Ward Leonard 400HP main motors installed on TESCO EMI Top Drives.



ACTION REQUIRED:

Note: The following procedure should be completed by a qualified TESCO technician, and followed up by a TESCO representative to ensure customers are aware of the change to the blower motor.

- 1. Check to verify the blower motor horsepower rating that is installed on the main 400HP top drive motor:
 - If a LeTourneau main motor is used and the blower motor is rated at 5HP, then no changes are required.
 - If a Ward Leonard main motor is used and the blower motor is rated at 10HP, the motor starter overload for the blower motor will need to be changed to a larger rating, TESCO part number 770791 (Starter,Motor,High Cap,5.5kW,13A, 3Ph) (Vendor number GPS1BHAL).
- 2. Reference drawing # 93100321 Rev6 and ECN-127-0477.
- 3. The TESCO project manager must notify customers of the blower motor being used on the main motor:
 - New EMI Top Drive customers have the option of replacing the main motor that uses the 10HP blower motor with a main motor that uses the 5HP blower motor, if required. Some conditions will apply.
 - For customers ordering multiple EMI Top Drives, ensure that the entire batch of main motors are using either a 5HP or 10HP blower motor (depending on customer requirements), not a combination of both.

Version	Date (D/M/Y)	ECN	Description of Bulletin Changes
Rev 0	28/05/2012	127-0482	Initial release of document

Copyright © 2012 Tesco Corporation. TESCO[®] is a registered trademark in the United States and Canada. TESCO CASING DRILLING[®] is a registered mark in the United States. CASING DRILLING[®] is a registered mark in the United States. Casing Drive System[®], CDS[®], Multiple Control Line Running System[®] and MCLRS[®] are trademarks in the United States.