



Technical Bulletin TB-014

From: Tesco Products – Applications

Date: May 29, 2003

Re: Hedland Flow Meter – COMPONENT RECALL

On May 1 2002 a Technical Bulletin, TB008, was distributed advising replacement of the following flow meters:

Tesco part number: 6719.

Description: 10 –100 GPM, uni-directional flow meter, Aluminum.

Supplier part number: H800A-100

Supplier: Hedland Flo-Tech, P.O. Box 1405, Racine Wisconsin.

Tesco part number: 0066.

Description: 10 – 100 GPM, bi-directional flow meter, reverse flow. Aluminum

Supplier part number: H800A-100-RF

Supplier: Hedland Flo-Tech, P.O. Box 1405, Racine Wisconsin.

These products are to be replaced with the following meter:

Tesco part number: 6208.

Description: 10 – 100 gallon per minute, bi-directional flow meter reverse flow, stainless steel.

Supplier part number: H800-100-RFS11

Supplier: Hedland Flo-Tech, P.O. Box 1405, Racine Wisconsin

It has been determined that in some applications a mechanical failure may occur in certain internal components. This failure can cause collateral damage in the closed loop hydraulic system. Hedland Flo-Tech has been working closely with Tesco Products to redesign this product to ensure that it will meet Tesco's operational standards.

If you have purchased any of these flow meters on or after **01/21/02** from Tesco Part Sales please contact Glenn Jones immediately at, 403-301-4200, to arrange for replacement components.

If you are unsure or have recently purchased a hydraulic Topdrive system please contact Mike Crocker for assistance.

***If there are any questions related to this Technical Bulletin please contact
Tesco Products-Applications immediately***

(403)-233-0757

[Mike Crocker Applications Group](#)